

High Accuracy Hygrometer-CP03U

Specification:

H Humidity **T** Temperature

Technical data		
	H	T
Measuring range	0.1~99.9%RH	-20~65.9°C
Accuracy	±2%RH(1%~90%RH)	±0.2°C(at 25°C)
Resolution	0.1%RH	0.1 °C
Display refresh time	1 minute	1 minute
Long Term Stability	≤0.25 (%RH/yr)	≤0.02 (°C/yr)
Common data		
Battery type	2 AAA batteries	
Weight	63g (battery included)	
Dimensions	Length x Width x Height: 68x25x45 mm	
Warranty	1 year	
Material/Housing	ABS	
Data logger	40,000 measuring values	
Software	CP03U reader	

*When display becomes vague, the battery is to be replaced.

*Please reload the batteries when the product crashed!

⚠ In fear of causing the meter to break down , please pay attention to the following warnings before usage **⚠**

- Please do not touch or clean the chip or the sensor!
- Please make sure the right polarity when changing batteries!
- Please do not use under corrosive or high-acid surroundings!
- This meter is not water-proof !

ACE DRAGON CORP.

Tel: +886-3-5985588

Fax: +886-3-5986366

<http://www.Dr-Storage.com>

E-mail: service@dr-storage.com

Address: 27, Gongye 5th Road, Hsinchu Industrial Park, 30352 Taiwan




CP03U

To PC or Notebook




CP03U

Humidity/Temperature data can be downloaded to PC through the USB connector and CP03U Reader.




- | | | | | | |
|---------------------------|------------------------------|--|---------------------------------|--|------------------------|
| 1 File | 2 Logger | | Data Acquisition | | Reduce |
| Open File | 3 Version | | Termination of data acquisition | | Enlarge |
| Save File | 4 Exit | | Tracking | | Floor Life Counter(V3) |
| Printer (Preview) (Print) | 5 Input text comment | | Display Mode (°C/°F) | | |
| Exit | 6 Setup interval time | | | | |



Logger

Setup: Setup: CP03U will clear old records and updates the date/time (important during first time usage).



Load: Download CP03U recorded temperature & humidity data to PC.